

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	2	4	2	4	2	4			
7	RR(E)	168	403		6		6		6			
8	Hyd	194	1044	1	11	1	11	1	11			
	Total	606	3055	3	21	3	21	3	21	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		5		5		5			
2	NLG	144	988									
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT				8		8		8			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	14	1	14	1	14	0	0	
	Grand Total	1082	6468	4	35	4	35	4	35	0	0	

TSSPDCL - LMRC / Corporate office

Date: 18.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MDK	Sadasivpet	Koheer	33KV	Sangareddy	16:15	18:25	2:10		Jumper Cut	Koheer	No
1	RR N	132KV LGM Pet	Aliabad	33KV	Medchal	7:30	11:35	4:05		4 Nos. Pin Insulator failed & Replaced at near LGM Pet	Aliabad	No
2		132KV LGM Pet	LGM Pet	33KV	Medchal	07.30	11.35	04.05		4 Nos. Pin Insulator failed & Replaced at near LGM Pet	LGM Pet	No
1	HYD N	132KV Gunrock	Hakimpet Cable-2	33KV	Nehrunagar	13.35	13.38	00.05	EL	Tripped on EL, feeder charged stood ok at 15:45 Hrs. Due to cable Punctred at 33/11KV Hakimpet SS. Work under Progress.	Hakimpet Cable-2	Alternate supply arranged. After isolated 33KV Hakimpet-Machhabollaram extension line

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Bijwar	PULIMAMIDI	11KV	Narayanpet	01.45	06.00	04.15		Tree touching to 11kv line at edivelli vlg	No
2		Mustipally	ANUGONDA	11KV	Narayanpet	04.10	08.00	03.50		LT line cut at anugonda vlg	No
3		KOSGI	CHENNARAM	11KV	Narayanpet	09.15	13.45	04.30		DTR fail at Chennaram vlg	No
4		MADDUR	DOREPALLY	11KV	Narayanpet	7:50	9:10	1:20		Pin binding fallen on through line at jadraopally vlg	No
5		NARAYANPET	JALALPUR	11KV	Narayanpet	03.30	07.00	03.30		11kv Jumper cut near ITI college	No
1	MDK	Bollaram - II	Kottam	11KV	Patancheru	8:56	10:40	1:44		Jumper Cut	No
1	SDPT	Gurralagondi	Gurralagondi	11KV	Siddipet	9:25	10:50	1:25		LC for Tree cutting LC No.18286	No
2		Kammarlapally	Kothapally	11KV	Siddipet	12.22	15.03	02.41		B/w for 11KV Pole Damage	No
3		Peddagundavelly	Balwanthapur	11KV	Siddipet	11.52	13.45	01.53		11 KV LINE Cut LC.no.0225	No
4		Mirdoddi	Mirdoddi	11KV	Siddipet	14.12	15.15	01.03		Tree Branch problem	No
5		KODAKANDLA SS	RAYAVARAM	11KV	Gajwel	11.40	12.55	01.15		11KV LINE CUT	No
6		MULUGU SS	MULUGU TOWN	11KV	Gajwel	07.45	09.10	01.25		TREE BRANCH FALLEN	No
7		DUDEEDA SS	INDUSTRIAL	11KV	Gajwel	18.14	19.12	00.58		TREE BRANCH FALLEN	No
8		Potharam	Potharam Rural	11KV	Husnabad	10:30	11:00	0:30		Tree fallen in line	No
1	RR N	Subhash Nagar	Meenakshi	11KV	Medchal	02.46	03.30	00.44		Lizards fallen on the 11KV Line at Springfield Colony	No
2		Shameerpet	Alankritha	11KV	Medchal	06.15	09.00	02.45		11KV Line AB Switch Opened at Alankrita Resorts(No Fault)	No
3		Shameerpet	Anthaipally	11KV	Medchal	07.15	10.35	03.20		11KV Pin Insulator failed & replaced at Pipes Company	No
4		Devarayamjal	Kottapet	11KV	Medchal	13:45	14:20	0:35		Tree Branch fallen on the 11KV Line at Rajendar Reddy Godam	No
1	RR E	Uppal	Adarsh nagar	11KV	Habsiguda	7:00	8:00	1:00		Kite stick & Tree branches fallen on 11kv line at Petrol bunk	No
2		Sai nagar	Maruthi nagar	11KV	Habsiguda	06.50	08.10	01.20		Bird fallen on 11kvline at Manikunta nagar	No
3		Mallapur	Mallapur Village	11KV	Habsiguda	06.55	08.35	01.40		100KVA T/F insulator fail at Meena nagar	No
4		Uppal kalsa	Shanthi nagar	11KV	Habsiguda	07.05	07.55	00.50		11KV line cut at Dwaraka appt	No
5		Street no 8	Ravinder nagar	11KV	Habsiguda	07.18	08.50	01.32		11 kv Line sanpped & 11KV pin insulator fail at sai baba temple ravinder nagar	No
6		Mallapur 2	Ashok nagar	11KV	Habsiguda	7:02	9:16	2:14		Tent house T/F insulator fail at Ashok nagar	No
1	HYD N	Gunrock	M.D.F	11KV	VI	12.30	13.55	01.25	EL,OL	DTR fault at More Super market	No
1	HYD S	Aliyabad	Police Quarters	11KV	III	00.46	02.15	01.29	EL	Removed loads of 11KV Chatrinaka fdr	No
2		Falaknuma	Chatrinaka	11KV	III	0:46	2:39	1:53	EL	No Visible Fault	Arranged B/F on 11KV Police Qtrrs feeder
3		Malakpet B-Block	Ekalavya Nagar	11KV	VIII	5:46	8:53	3:07	OL-R&Yph	Cable fault at Ekalavya Nagar & Faulty 11KV Madannapet feeder loads	No
4		Moosarambagh	Dwarakapuram	11KV	VIII	6:45	8:31	1:46	EL,OL-Rph	Tree branches fallen on lines & Pin Insulator flash over at Dwarakapuram	No
5		Aliyabad	Shamsheergunj	11KV	III	06.56	09.57	03.01	OL-Bph	Cable fault at Ali Nagar Janda & Tree branches fallen on lines at Aman Nagar	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	HYD C	Bathkamma Kunta	Ahobilmutt	11KV	II	06.45	08.15	01.30	EL	Pin Insulator flash over at Azam House	No
2		Industrial Area	Barkathpura	11KV	II	06.59	08.00	01.01	EL	Tree branches fallen on lines at Barkathpura	No
3		Zamistanpur	L.N.Nagar	11KV	II	07.08	08.48	01.40	EL	Tree branches fallen on lines & Disc Insulator flash over at L.N.Nagar Nala	No
4		ITI Mallepally	Zaheera Masjid	11KV	VII	7:38	8:53	1:15	EL	Tree branches fallen on lines at Royal Sweet House	No
5		Chilkaiguda	44 Bus Stop	11KV	II	07.42	09.50	02.08	EL	Tree branches fallen on lines at MCH Park	No