

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		2		2		2			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		10		10		10			
	Total	606	3055	0	13	0	13	0	13	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	6	7	6	7	4	7	2		2 No.s 33KV still
2	NLG	144	988		9		9		9			
3	MDK	107	933									
4	SDPT				4		4		4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	6	20	6	20	4	20	2	0	
	Grand Total	1082	6468	6	33	6	33	4	33	2	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 19.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	220/132KV SS Palkonda	Janampet	33KV	Mahabubnagar	22.07	22.47	00.40	E/L	Due to Heavy Wind&Rain	Janampet	-
2		Makthal	Krishna	33KV	Narayanpet	21.25	22.30	01.05	E/L	Due to Heavy Wind&Rain	Krishna	-
3		Maddur	Vepoor	33KV	Narayanpet	22.15	7.40 (20.05.21)	09.25	E/L	Due to Heavy Wind&Rain	Vepoor	-
4		Ghanapur	Lattupally	33KV	Wanaparthi	17.45	18.00	00.15	E/L	Due to Line Problem	Lattupally	Alternate supply arranged from 132KV Nagarkurnool 33KV Bijinepally feeder at 18:00Hrs.
5		Thirumalaipally	Kurumurthy	33KV	Wanaparthi	21.55	00.00	02.05		Not Rectified	Kurumurthy	-
6		Thirumalaipally	Madanapur	33KV	Wanaparthi	21.55	00.00	02.05		Not Rectified	Madanapur	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 19.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Manthangoud	KATHWAR	11KV	Narayanpet	07.25	10.45	03.20		LT line touched to 11KV Line at Kathwar(V)	-
2		KOSGI	CHENNARAM	11KV	Narayanpet	05.40	08.59	03.19		11KV Jumper cut at chennaram(V)	-
3		KOSGI	CHENNARAM	11KV	Narayanpet	09.51	10.39	00.48		11KV Line top touched to channel at chennaram(V)	-
4		KOSGI	SAMPALLI	11KV	Narayanpet	13.15	14.35	01.20		11KV line top touched to channel at thimmaipally(V)	-
5		MARIKAL	ELIGANDLA	11KV	Narayanpet	06.00	08.30	02.30		Due to 5 AGL DTR Bit cutting near Eligandla(V)	-
6		Badepally	Burgupally	11KV	Jadcherla	08.45	11.15	02.30		Due to 11 KV Jumper cut near Kistampally(V)	-
7		Midjil	Boinpally	11KV	Jadcherla	07.15	10.20	03.05		11 KV line Phase to Phase near High School Road	-
1	NLG	Kasarabada	T.K Pahad	11KV	Suryapet	07.30	10.50	03.20	E/L	11Kv Conductor snapped	-
2		Chervupally	Dacharam	11KV	Nalgonda	06.30	08.15	01.45	E/L	11KV Jumper cut	-
3		Koppole	Koppole	11KV	Nalgonda	08.05	11.25	03.20	E/L	11KV Jumper cut	-
4		Agamothkur	Bommakal	11KV	Miryalguda	08.56	13.38	04.42	E/L	11KV jumper cut near village	-
5		Pulicherla	Pulicherla	11KV	Miryalguda	12.02	17.20	05.18	E/L	DTR failed and AB jumper cut	-
6		Pottichalma	Chalukurthy	11KV	Miryalguda	02.10	08.15	06.05	E/L	11KV jumper cut near out skirts	-
7		P D Pally	P D Pally	11KV	Miryalguda	05.00	08.55	03.55	E/L	11KV conductor phase to phase due to heavy wind and gale	-
8		P D Pally	Gajalapuram	11KV	Miryalguda	05.00	08.55	03.55	E/L	11KV conductor phase to phase due to heavy wind and gale	-
9		Kamareddy gudem	Pusalapad	11KV	Miryalguda	04.00	10.40	06.40	E/L	11KV jumper cut near (V)	-
1	SDPT	Bejgama SS	Bejgama Feeder	11KV	Gajwel	7:00	9:05	02.05		11 KV line cut	-
2		Dommata SS	Gajulapally LC: 7893 Srinivas CL	11KV	Gajwel	15.31	17.26	01.55		Tree Branch Fallen	-
3		THOTAPALLY	DEVAKKAPALLI	11KV	Husnabad	04.48	02.24	12.00		B.D , INSULATOR FAILURE	-
4		Nagapuri	Pothireddypalli	11KV	Husnabad	07.40	07.40	00.00		B.D , LINE CUT	-
1	RR N	HM T	Manikyanagar	11KV	Medchal	23.02	00.17	01.15	EL	Tree fallen on the 1kv Line at Vaninagar	-
2		UMCC	Crusher	11KV	Medchal	22.45	23.35	00.50	EL	11 kv AB cable sparked at Kaiser Nagar	-
1	RR E	AS Rao Nagar	Gandhi Nagar	11KV	Sainikpuri	14.34	15.44	01.10		Tree branches fallen on 11Kv line at Gandhi Nagar	-
1	HYD N	Clock Tower	Natraj	11KV	V	12.40	14.20	01.40	OL-Bph	Tree branches fallen on lines at Natraj Theater	----
2		James Street	Asrani Hotel	11KV	V	23.00	00.20	01.20	EL,OL-Rph	Pin Insulator flash over at M.G Road Signal	Arranged B/F on 11KV Nakshatra fdr
3		Tirumalagiri	Chinna Kamela	11KV	C-VI	22.38	00.15	01.37	EL	Jumper cut at Mahankali Temple	----
4		Gunrock	Tirumalagiri	11KV	C-VI	23.05	00.50	01.45		Bird fault on lines & B/o Brass Patti at Maruthi Showroom	----
5		Nehru Nagar	LIC Colony	11KV	C-VI	23.15	00.55	01.40	EL,OL-R&Yph	Tree branches fallen on lines at LIC Colony	----
6		Bora Banda	Banjara Nagar	11KV	IV	23.20	01.05	01.45	EL	AB Cable fault at Haji Masthan Bakery	----
7		Addagutta	Hanuman Temple	11KV	C-VI	23.55	01.00	01.05	EL,OL-Yph	Pin Insulator flash over at Hanuman Temple	----
8		Tirumalagiri	Officers Colony	11KV	C-VI	22.36	01.30	02.54	EL,OL-Bph	Tree branches on lines at Hanuman Temple	----
9		Marredpally	Jyothi colony	11KV	C-VI	23.10	02.45	03.35	EL	Post type Insulator flash over at Jyothi Colony	----
1	HYD S	Moosarambagh	SBI Colony	11KV	VIII	22.13	23.46	01.33	EL	Disc Insulator flash over at Maruthi Classic Apartment	----