

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403									
8	Hyd	194	1044	1	4	1	4	1	4			
	Total	606	3055	1	7	1	7	1	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	4	1	4	1	4			
2	NLG	144	988		1		1		1			
3	MDK	107	933									
4	SDPT											
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	1	5	1	5	1	5	0	0	
	Grand Total	1082	6468	2	12	2	12	2	12	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 23.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Thirumalaipally	Kurumurthy	33KV	Wanaparth	00.44	13.25	12.41	E/L	3 No Insulator Failed and Cable Kit Damaged at Madanapur Railway Birdge	Kurumurthy	-
1	HYD N	132KV Gunrock-33KV Airport	33KV Airport	33KV	Bowenpally	08.45	09.00	00.15	EL+ OL B ph	Tripped on EL OL Bph,alternate supply arranged patrolling done by AE/L/Bowenpally no visible fault found idle feeder charged stood ok at 10:45 hrs	33KV Airport	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 23.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Hanwada	Budaram	11KV	Mahabubnagar	09.00	13.00	04.00		11KV Tree Fallen on Conductor at Budaram	-
2		Hanwada	Madaram	11KV	Mahabubnagar	07.00	09.00	02.00		11KV Tree Fallen on Conductor at Madaram	-
3		Kurumurthy	Appampally	11KV	Mahabubnagar	10.25	12.38	02.13		11KV Line Phase to Phase at Appampally	-
4		Kurumurthy	Ammapur	11KV	Mahabubnagar	10.30	12.40	02.10		11KV Line Phase to Phase at Alipur	-
1	NLG	Yerkaram	Rajnaik thanda	11KV	Suryapet	13.40	15.20	01.40	E/L	Tree branch fallen on the 11Kv line	-
1	RR N	GP Pally	APIIC	11KV	Medchal	08.55	09.45	00.50	BD	DTR AB Switch Sparked and rectified at Sacks Company	-
2		Aliabad	HBL	11KV	Medchal	09.10	10.30	01.20	BD	Tree Fallen on 11KV Line at Sangeetha Function Hall	-
3		Bommarajpet	Ramalayam	11KV	Medchal	12.40	14.25	01.45	BD	11KV Pole Damaged by Lorry at Bommarajpet Village(11KV Jumper Opened)	-
1	HYD N	Clock Tower	Sangeeth	11KV	V	05.59	08.35	02.36	All Indication	Suspetcted Cable fault	Arranged B/F on 11KV St.Marry fdr
2		Clock Tower	Station Road	11KV	V	05.59	08.20	02.21	All Indication	Suspetcted Cable fault	Arranged B/F on 11KV Rly. Reservation & 11KV Gurudwara feeders
1	HYD C	Industrial Area	Barkathpura	11KV	II	3:15	4:20	1:05	EL	Tree branches fallen on lines at Padma Colony	-----
2		A.C.Guards	Bazarghat	11KV	VII	18:30	19:40	1:10	EL	Pin Insulator flash over at Niloufer Hospital	-----