

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403									
8	Hyd	194	1044		1		1		1			
	Total	606	3055	0	2	0	2	0	2	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	5	8	5	8	5	8			
2	NLG	144	988		4		4		4			
3	MDK	107	933	2	3	2	3	2	3			
4	SDPT			1	19	1	19	1	19			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	8	34	8	34	8	34	0	0	
	Grand Total	1082	6468	8	36	8	36	8	36	0	0	

TSSPDCL - LMRC / Corporate office

Date: 26.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Machanpally	33KV	Mahabubnagar	16.40	18.28	01.48	O/L	Due to Heavy Wind	Machanpally	Alternate supply given from 33KV Kodur at 18:28Hrs.
2		Midjil	Madaram	33KV	Jadcherla	12.50	16.55	04.05	O/L	Jumper Cut on the Line	Madaram	No
3		Balanagar	Rajapur	33KV	Jadcherla	04.45	08.10	03.25	E/L&O/L	Tree fallen on the line nea Thirumalapur (V)	Rajapur	No
4		Balanagar	Rajapur	33KV	Jadcherla	15:40	16:20	0:40	O/L	Tree fallen on the line at Khanapur(V)	Rajapur	No
5		Maddur	Kothapally	33KV	Narayanpet	16.40	20.20	03.40	E/L	Pin insulator failed near Gudmal SS	Kothapally	No
1	MDK	Jogipet	G.Peddapur	33KV	Jogipet	13:25	14:05	0:40		Due to insulator failure	G.Peddapur	No
2		Pashamailaram	Suven life science	33KV	Sangareddy	14.40	19.00	04.20		Due to insulator failure	Suven life science	No
1	SDPT	Habsipur	Pothareddypet	33KV	Siddipet	15:42	16:07	0:25		Tree branches touched to the 33KV line	Pothareddypet	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Paspula	PASUPULA BHEEMA LIFT	11KV	Narayanpet	06.10	10.24	04.14		Tree branch fallen on 11kv line at pasupula vlg	No
2		KOSGI	BHAKTIMALLA (HANMANPALLI)	11KV	Narayanpet	15.10	17.20	02.10		Tree branch fallen on 11kv line near masaipally vlg	No
3		PALLERLA	NADIPAD	11KV	Narayanpet	11.30	14.51	03.21		11kv line and LT line touched each other at pallerla vlg	No
4		GOKULNAGAR	GOKULNAGAR	11KV	Narayanpet	16:40	18:20	1:40		11kv line cut at gokulnagar vlg	No
5		NARAYANPET	NARAYANPET TOWN (CIVIL)	11KV	Narayanpet	8:45	9:35	0:50		Tree branch fallen on 11kv line at subhash road	No
6		PERAPALLA	PERAPALLA	11KV	Narayanpet	0:15	6:15	6:00		Tree branch fallen on 11kv line	No
7		Marikal	Malkapur	11KV	Jadcherla	1:05	7:20	6:15		11KV Jumper cut near Malkapur	No
8		Udithyal	Udithyal	11KV	Jadcherla	10.09	15.10	05.01		11KV Wire cut near Veerann apally	No
1	NLG	Madgulapally	Kukkadam	11KV	Nalgonda	15:00	16:10	1:10	EL	insulator failed	No
2		Thungathurthy	B Ramaram	11KV	Suryapet	08.00	11.20	03.20	EL	insulator failed	No
3		Kudakuda	MG Nagar thanda	11KV	Suryapet	09.40	12.30	02.50	EL	Conductor snapped	No
4		Nandanam	Anajipur	11KV	Bhongir	11.15	12.15	01.00	EL	11KV Insulator Failed near Anajipur Village	No
1	MDK	Pati	My Home	11KV	Sangareddy	12:40	16:38	3:58		Due to jumper cut	No
2		Pati	ION Exchange	11KV	Sangareddy	12.40	13.20	00.40		Due to jumper cut	No
3		Bollaram - II	Kottam	11KV	Patancheru	19.10	19.50	00.40		Due to tree branch fallen on the line	No
1	SDPT	Thornala	Appanapally	11KV	Siddipet	13:34	16:50	3:16		11KV Insulator failed	No
2		Ramancha	Ramancha	11KV	Siddipet	09.30	11.30	02.00		11KV Wire cut	No
3		Dubbak	Lachapet	11KV	Siddipet	11.54	17.20	05.26		11KV Wire cut	No
4		Mirdoddy	Mirdoddy	11KV	Siddipet	11.17	12.41	01.24		Tree branches fallen on the line, LC No. 23465	No
5		Ragothampally	Gosanpally	11KV	Siddipet	11.15	19.30	08.15		11KV Line cut, LC 15668	No
6		Gajwel -Pregnapur	Town-I	11KV	Gajwel	10:56	12:30	1:34		Jumper Cut	No
7		Gajwel	Mutrajpally	11KV	Gajwel	11:25	12:25	1:00		insular failed	No
8		Gajwel	Mutrajpally	11KV	Gajwel	13:30	15:30	2:00		Tree has fallen 11KV line	No
9		Ganeshpally	Angadikistapur	11KV	Gajwel	17.30	18.45	01.15		11KV line was fallen LT line	No
10		Mulugu	Town	11KV	Gajwel	08.50	09.50	01.00		11KV Jumper cut near SS	No
11		Mulugu	Nagireddy pally	11KV	Gajwel	09.25	10.34	01.09		11KV Insulater fail	No
12		Mulugu	Narsampally	11KV	Gajwel	12.43	14.00	01.17		11KV line cut	No
13		Vantimamidi	R&R Colonay	11KV	Gajwel	15.25	16.15	00.50		Tree has fallen 11KV line	No
14		Cheela Sagar	Annasagar	11KV	Gajwel	09.00	12.30	03.30		Tree branches fallen on the line	No
15		Dommeta	Gajulapally	11KV	Gajwel	08.34	10.20	01.46		Tree branches fallen on the line	No
16		Mubharasapur	Thirumalapur	11KV	Gajwel	10.45	11.30	00.45		HT/LT work	No
17		Raipole	Kothapally	11KV	Gajwel	12.40	13.40	01.00		11KV line cut	No
18		Potharam	Potharam rural	11KV	Husnabad	15.15	16.00	00.45		Jumper cut	No
19		Thotapally	Thotapally rural	11KV	Husnabad	9:50	13:50	4:00		3-ph break down Jumper cut	No
1	RR N	DP Pally	IDA	11KV	Jeedimetla	14:00	15:15	1:15	EL/OL	11kv line Cut at AksharaSchool, IDA	No
1	HYD S	C.R.P.F.	Maisaram	11KV	III	02.54	05.52	02.58	EL,OL	Cable fault at Maisaram	Arranged B/F on 11KV Omer Colony feeder & 11KV Salala feeder