

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		1		1		1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		5		5		5			
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	1	1	1	1	1			
2	NLG	144	988		6		6		6			
3	MDK	107	933	1	3	1	3	1	3			
4	SDPT			1	16	1	16	1	16			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	3	26	3	26	3	26	0	0	
	Grand Total	1082	6468	3	33	3	33	3	33	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 28.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Hanwada	33KV	Mahabubnagar	05.02	05.32	00.30	E/L	Tree Fallen on the Line at Hanwada		NO
1	MDK	Jogipet	G.Peddapur	33KV	Jogipet	00.05	08.05	08.00		BD due to 33KV Pole Damaged		-
1	SDPT	Shanigaram	Ramchandrapur	33KV	Husnabad	14.55	17.55	03.00		BD due to Pin binding failed		-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 28.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Pediripad	11KV	Narayanpet	07.30	13.15	05.45		Due to DTR Failed at Pediripad(V)	-
1	NLG	Penpahad	SR Palem	11KV	Suryapet	07.00	10.05	03.05	E/L	Jumpur cut & line melt	-
2		Thungathurthy	B Ramaram	11KV	Suryapet	08.00	11.45	03.45	E/L	Insulator failed	-
3		Palakeedu	Palakeedu	11KV	Huzurnagar	02.20	08.00	05.40	EL	11 KV LINE SNAPPED	-
4		Peddathanda	Pallepahad	11KV	Bhongir	03.10	10.15	07.05	EL/OL	63 kva DTR Failed near Palepahad village.	-
5		Aror	Aror Agl	11KV	Choutuppal	05.45	07.45	02.00	EL/OL	11 kv Disc failed near Aror village	-
6		Baironibanda	Ramanujapuram	11KV	Nalgonda	03.30	07.05	03.35	EL/OL	11KV line cut at near SS-9	-
1	MDK	Cheryal	Turbovent	11KV	Sangareddy	19.24	22.00	02.36		BD due to Insulator failed	-
2		Anrich Bollaram	Town-II	11KV	Patancheru	00.00	00.58	00.58		BD due to Insulator failed	-
3		Gundla Machnoor	Arch Pharma	11KV	Jogipet	15.55	16.55	01.00		BD due to Insulator failed	-
1	SDPT	Gajwel SS	Mutrajpally feeder	11KV	Gajwel	04.00	13.00	09.00		TREE BRANCH FALLEN	-
2		Gajwel SS	Jaligama feeder	11KV		05.00	06.00	01.00		JUMPER CUT	
3		Gajwel SS	Jaligama feeder	11KV		06.35	13.20	06.45		CT FAILED	
4		Pregnapur SS	Akkaram feeder	11KV		11.15	12.57	01.42		COPPER PATTI CUT	
5		GOWRARAM SS	Gowraram Town 2	11KV		04.35	06.00	01.25		TREE BRANCH FALLEN	
6		Mulugu SS	Mulugu Head Quaeter	11KV		00.00	01.30	01.30		TREE BRANCH FALLEN	
7		Marpadaga SS	Sirisingandla Agl	11KV		01.00	04.00	03.00		DISK FAILED	
8		Marpadaga SS	Sirisingandla Agl	11KV		04.45	09.35	04.50		DISK FAILED	
9		Marpadaga SS	Nagireddypally Agl	11KV		01.45	04.00	02.15		TREE BRANCH FALLEN	
10		Duddeda SS	Industrial feeder	11KV		00.30	05.15	04.45		TREE BRANCH FALLEN	
11		Duddeda SS	Town feeder	11KV		01.00	03.05	02.05		TREE BRANCH FALLEN	
12		Pandilla	pandilla Express	11KV		07.00	08.09	01.09		INSULATOR FAILURE	-
13		Ramchandrapur	Vinjalpaly	11KV		10.30	11.30	01.00		INSULATOR FAILURE	-
14		REGULAPALLY	Regulapally(T)	11KV		11.40	13.20	01.40		LINE SNAPPED	-
15		Rebarthy	Rebarthy	11KV		20.05	21.10	01.05		JUMPER CONNECTION FAILED	-
16		Arjunpatla	Kamalaipally	11KV		01.00	09.00	08.00		LINE SNAPPED	-
1	RR N	Kistapur	IDA Hanuman	11KV	Medchal	05.55	07.15	01.20	BD	11KV Conductor Snapped and replaced at Ravalkole Common	-

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	RR E	Malkajiri	Dayanand Nagar	11KV	Sainikpuri	03.55	05.15	01.20		11KV Pin Insulator failed at Vani nagar (AE)	-
1	HYD N	Clock Tower	Station Road	11KV	V	03.20	05.30	02.10	EL,OL	2Nos. HT Services fault	Arranged B/F on 11KV Gurudwara fdr
2		New Bowenpally	Lions Club Raju Colony	11KV	VI	03.37	04.50	01.13	EL	Pin Insulator flash over at Durga Temple	----
3		Lalaguda	Chenna Reddy	11KV	V	11.00	12.25	01.25	A/R Tripped	No Visible Fault	----
4		Clock Tower	Anjali	11KV	V	11.23	12.30	01.07	EL,OL-Bph	Cable fault & Faulty DTR at Anjali (1No. DTR kept off)	At 12:05 Hrs Partial loads added on 11KV Minerva fdr
1	HYD S	Kulsumpura	Maha Laxmi Nagar	11KV	IX	21.04	22.15	01.11	EL	Pin Insulator flash over at Kummariwadi	-