

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550		3		3		3			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044									
	Total	606	3055	0	4	0	4	0	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849		3		3		3			
2	NLG	144	988		5		5		5			
3	MDK	107	933	1	1	1	1	1	1			
4	SDPT			1	4	1	4	1	4			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	13	2	13	2	13	0	0	
	Grand Total	1082	6468	2	17	2	17	2	17	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 29.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDP	Shanigaram	Chalimeda	33KV	Siddipet	00.25	10.55	10.30		Pole no. 135 damaged due to lorry accident replaced near Gagillapur SS	Chalimeda	-
1	MDK	Sadasivpet	Majeera	33KV	Sangareddy	14.35	17.55	03.20		B/D due to Jumper cut	Majeera	-

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 29.05.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	MADDUR	DOREPALLY	11KV	NARAYANPET	07.45	09.21	01.36		Due to Disc Fail ontigunta thanda	-
2		MARIKAL	TILERU	11KV	NARAYANPET	14.40	15.25	00.45		Due to 11KV Line Phase to Phase	-
3		MARIKAL	P.C.KUNTA	11KV	NARAYANPET	15.30	17.30	02.00		Due to one bit cutting	-
1	NLG	Adivemula	Thimmapuram	11KV	Suryapet	07.00	08.20	01.20	E/L	Line mel HT/LT	-
2		Jalalpuram	Jalalpuram	11KV	Suryapet	04.30	08.04	03.34	E/L	Insulator flashover	-
3		Palakeedu	Nagireddy gudem	11KV	Huzurnagar	07.05	08.30	01.25	E/L	11 KV LINE SNAPPED	-
4		Munagala	Barakathgudem	11KV	Huzurnagar	10.20	11.30	01.10	E/L	11 KV JUMPER CUT	-
5		Choutuppal IPDS	Damera Agl	11KV	Choutuppal	07.57	09.58	02.01	E/L	25 kva Dtr failed near Thangedipally village	-
1	SDP	Laxmidevipally	Ibrahimpur	11KV	Siddipet	10.40	11.40	01.00		B/D HT/LT line problem Lcno. 18449	-
2		Cherial Town	Cherial-Town	11KV	Husnabad	18.20	18.50	00.30		Tree fallen on line	-
3		Mustyal	Chuchanakota	11KV	Husnabad	18.00	21.20	03.20		Tree fallen on line	-
4		Guruvannapet	Guruvannapet	11KV	Husnabad	06.40	08.45	02.05		Tree fallen on line	-
1	MDK	Patancheru Town	MIA-I	11KV	Ptancheru	05.55	07.10	01.15		BD due to Tree branches fallen on the line	-
1	RR N	Dulapally	Dulapally Village	11KV	Medchal	11.41	12.05	00.24	BD	11KV Line AB Switch opened at CMR Collage road (11KV Line Touched to the Pole)	-
2		Devarayamjal	DMC	11KV	Medchal	07.20	08.50	01.30	BD	Tree fallen on 11KV Line at Dog farm	-
3		Gowdavelly	Ayodhya	11KV	Medchal	16.10	17.40	01.30	BD	11KV Jumper cut and touched to LT line and Rectified at Ayodya X Road	-
1	RR E	Kushaiguda	Mahesh Nagar	11KV	Sainikpuri	12.15	13.15	01.00		11Kv jumper cut at Narsing Cloth Showroom Mahesh Nagar (AE/OP)	-