

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107									
2	NLG	22	358									
3	MDK	97	359									
4	SDPT											
5	RR(S)	53	234									
6	RR(N)	54	550	1	1	1	1	1	1			
7	RR(E)	168	403		1		1		1			
8	Hyd	194	1044		2		2		2			
	Total	606	3055	1	4	1	4	1	4	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849									
2	NLG	144	988		6		6		6			
3	MDK	107	933		3		3		3			
4	SDPT			2	30	2	30	2	30			
5	RR(S)	58	396									
6	RR(N)	38	114									
7	RR(E)	22	133									
	Total	476	3413	2	39	2	39	2	39	0	0	
	Grand Total	1082	6468	3	43	3	43	3	43	0	0	

TSSPDCL - LMRC / Corporate office

Date: 30.05.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	SDPT	Musthyala	Dhoolmitta	33KV	Husnabad	12:55	14:40	1:45		Line problem	Dhoolmitta	No
2		Shanigaram	Bejjanki	33KV	Husnabad	00.10	01.10	01.00		Heavy wind and rain	Bejjanki	No
1	RR N	132KV Medchal	Keshavaram	33KV	Medchal	8:25	9:08	0:43		33KV Cable End Kit Failed at Pudur SS (33KV Line AB Switch Opened)	Keshavaram	No

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	NLG	Pamanagundla	Ismaipally	11KV	Nalgonda	05.35	08.50	03.15	EL	Trees Fallen on the 11 KV Line	No
2		Pamanagundla	Yerrasanigudem	11KV	Nalgonda	05.35	10.56	05.21	EL	11KV line cut	No
3		Eduloor	Parada	11KV	Nalgonda	08.30	10.30	02.00	EL	11KV line cut	No
4		MR.Gudem	Gangasanipally	11KV	Bhongir	6:00	9:00	3:00	EL	11 KV Insulator failed near Gangasanipally village	No
5		Ch.Laxmapur	Malkapur	11KV	Bhongir	4:33	10:10	5:37	EL	11 kv Insulator failed near Pokya thanda	No
6		Rajapeta	Nemia Agl	11KV	Bhongir	04.00	09.00	05.00	EL/OL	11 kv Line snapped near nemila village	No
1	MDK	Kythan	Kythan	11KV	Patancheru	9:06	10:30	1:24		Conductor Snapped	No
2		Sulaxshana-I	Sulaxshana-I	11KV	Patancheru	15.20	16.20	01.00		Jumper Cut	No
3		Rupa	Rupa	11KV	Patancheru	09.06	12.26	03.20		Conductor Snapped	No
1	SDPT	Narmetta	Narmetta AGL	11KV	Siddipet	09.00	13.00	04.00		11KV Disc failed	No
2		Peddakodur	Peddakodur	11KV	Siddipet	03.00	07.00	04.00		Heavy wind and rain	No
3		Narayanraopet	Beerappagudi	11KV	Siddipet	08.44	09.58	01.14		Heavy wind and rain	No
4		Laxmidvipally	Ibrahimipur	11KV	Siddipet	07.15	09.45	02.30		Heavy wind and rain	No
5		Gambeerpur	Gambeerpur	11KV	Siddipet	03.02	06.05	03.03		Heavy wind and rain	No
6		Peddacheppyal	Alwal	11KV	Siddipet	04.00	07.00	03.00		Heavy wind and rain	No
7		PAMULAPARTHY	INDIRANAGAR	11KV	Gajwel	11:40	12:40	01.00		11 KV BUSH CUT	No
8		GOWRARAM	TOWN-2	11KV	Gajwel	00:10	2:10	2:00		Tree branches fallen on the 11KV line	No
9		MULUGU	NAGIREDDYPALLY	11KV	Gajwel	10.28	12.48	02.20		INSULATOR FAILED	No
10		VANTIMAMIDI	R & R COLONY	11KV	Gajwel	00.03	09.50	09.45		JUMPER CUT	No
11		VANTIMAMIDI	INDUSTRIAL	11KV	Gajwel	06.50	10.43	03.33		11 KV LINE CUT	No
12		KONDAPAKA	VISHWANATHPALLY	11KV	Gajwel	06.30	10.30	04.05		DISC FAILED	No
13		KONDAPAKA	NACHARAM	11KV	Gajwel	10.30	11.30	01.00		DISC FAILED	No
14		DOULTHABAD	TOWN	11KV	Gajwel	15.20	15.30	00.10		DISC FAILED	No
15		MACHANPALLY	MACHANPALLY	11KV	Gajwel	14.38	17.53	03.16		11 KV POLE DAMAGE WORK	No
16		MD SHAPUR	SHUT DOWN	11KV	Gajwel	01.30	07.00	05.30		LV AB CORE INSULATOR FAILED	No
17		Bekkal	Kondapur	11KV	Husnabad	00.00	07.30	07.30		Break down due to rain	No
18		Bekkal	Kutigal	11KV	Husnabad	00.00	05.50	05.50		Break down due to rain	No
19		Komuravelly	Rebarthy & Iadnur	11KV	Husnabad	03.30	08.50	05.20		Line cut	No
20		Komuravelly	Kadaverugu	11KV	Husnabad	01.00	06.25	05.25		Tree fallen on the line	No
21		Komuravelly	Inapur Agl	11KV	Husnabad	17.45	18.22	00.37		Jumper cut	No
22		Chityala	Dommata	11KV	Husnabad	00.00	13.40	13.40		Break down due to rain	No
23		Chityala	Thadoor	11KV	Husnabad	00.00	04.30	04.30		Tree fallen on the line	No
24		Chityala	Chityala	11KV	Husnabad	00.00	04.30	04.30		Tree fallen on the line	No
25		Gurjakunta	Gurjakunta TOWN	11KV	Husnabad	00.30	03.00	02.30		Break down due to rain	No
26		Gurjakunta	Gurjakunta TOWN	11KV	Husnabad	06.30	09.40	03.10		Insulator failed	No
27		Akunoor	Akunoor	11KV	Husnabad	06.30	11.30	05.00		Jumper cut	No
28		Husnabad	Madatha	11KV	Husnabad	07.20	09.30	02.10		Disc failed	No
29		Gandipally	Ramavaram	11KV	Husnabad	01.40	05.40	04.00		Break down due to rain	No
30		Gandipally	Nandaram	11KV	Husnabad	00.40	08.00	07.20		Break down due to rain	No
1	RR N	Aleap	Pragathinagar	11KV	Medchal	13:13	14:35	1:22		11kv AB cable Failure at Pt-No-410 Pragathinagar	No
1	RR E	Uppal	Raghavendra nagar	11KV	Habsiguda	8:05	8:55	0:50		chameleon fallen on T/F at Annapurna bus stop	No
1	HYD S	Salarjung	Madina	11KV	III	20.33	23.00	02.27	EL	UG Cable fault at B.G.Market & Relay fault at SS	Arranged B/F on 11KV Gansi Bazar fdr & 11KV Pather Gatti fdr
2		Salarjung	City College	11KV	III	21:05	23:00	1:55	EL	No Visible Fault	Arranged B/Fon 11KV Darulshifa fdr