

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	4	0	4	0	4	0	0	
6	RR(N)	54	550	0	5	0	5	0	5	0	0	
7	RR(E)	168	403	0	6	0	6	0	6	0	0	
8	Hyd	194	1044	0	6	0	6	0	6	0	0	
	Total	606	3055	0	21	0	21	0	21	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	3	1	3	1	3	0	0	
2	NLG	144	988	3	8	3	8	3	8	0	0	
3	MDK	107	933	1	0	1	0	1	0	0	0	
4	SDPT			1	6	1	6	1	6	0	0	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	Total	476	3413	6	17	6	17	6	17	0	0	
	Grand Total	1082	6468	6	38	6	38	6	38	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 03.09.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Polepally	Mission Bhagiratha	33KV	Jadcherla	10.00	15.20	05.20	E/L&O/L	33KV Pole Damaged & New Pole Replacement at Mission Bhagirata		No
2	Nalgonda	Aitipamula	Arlagadagudam	33KV	Nalgonda	01.12	07.30	06.18	EL	Haevy Rain		
3	Suryapet	Kodad	Akupamula	33KV	Huzurnagar	05.00	08.30	03.30		33 kv Conductor snapped		
4	Suryapet	Kusumanchi	Mamillagudem	33KV	Huzurnagar	06.05	08.55	02.50		33 KV Disk failed		
5	Sangareddy	Sadasivpet	Jogipet	33KV	Sangareddy	21.30	23.25	01.55		B/D Due to Jumper Cut		
6	Siddipet	Doulthabad	Gurrlasofa	33KV	Gajwel	09.10	10.47	01.37		BD(AB Switch Spark)		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 03.09.2021

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Konded	Chinna Adirala	11KV	Jadcherla	06.55	15.20	08.25		B.D.Dtr Problem At Chinna Adirala Cheruvu Side.	
2	MBNR	Marikal	Chakalpally	11KV	Jadcherla	05.45	11.54	06.09		BD 11KV Insulator Failure Near Kachhala Madugu Tanda.	
3	MBNR	Annasagar	Annasagar	11KV	Jadcherla	08.05	10.59	02.54		B.D.11Kv Insulator Failure Near Annasagar (Vi).	
4	Nalgonda	Kethepally	Inupamula	11KV	Nalgonda	06.35	09.15	02.40	EL	11KV line Jumper Cut And Pin Insuletor Failed	
5	SURYAPET	Penpahad	S.R Palem	11KV	SURYAPET	07.20	10.30	03.10		Insulator failed	
6	SURYAPET	Garidepally	L B Nagar	11KV	Huzurnagar	07.30	09.00	01.30		11 KV LINE SNAPPED	
7	SURYAPET	Mattampally	Allipuram	11KV	Huzurnagar	03.40	07:00	03.20		11 KV JUMPET CUT	
8	SURYAPET	Keethavarigudem	Rainigudem	11KV	Huzurnagar	03.00	07.30	03.30		11 KV LINE SNAPPED	
9	SURYAPET	Akupamula	Akupamula	11KV	Huzurnagar	03.35	06.00	02.25		11 KV Disk failed	
10	Yadadri	Malkapur	Malkapur Indl	11KV	Choutuppal	23.39	01.38	01.59		11 kv Line snapped at Jaya lab near Malkapur village	
11	Yadadri	Veluvarthy	Sunkishala	11KV	Choutuppal	10.20	10.55	00.35		11kv Insulator Failed near Kerchpally Road	

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
12	Habsiguda	Stno:8	Green Hills	11KV	Habsiguda	23.51	02.10	02.19		Post of insulater failed at Bora Appartment at Sneha Nagar	
13	Habsiguda	IDA Uppal	Sri Krishna	11KV	Habsiguda	14.10	15.00	00.50		11KV Line snapped at Hunuman Temple	
14	Habsiguda	Singapoor City	RGK	11KV	Keesara	12.00	13.00	01.00		Pin Insulator failed at Royal foot APT	
15	Habsiguda	Singapoor City	Singapoor-I	11KV	Keesara	01.00	02.00	01.00		Insulator failed at D4 35 Block	
16	Medchal	Aliabad	Majeedpur	11KV	Medchal	05.20	06.05	00.45		Tree fallen on 11 KV OH line at Majeedpur (V)	
17	Medchal	Deveryanjai	DMC	11KV	Medchal	02.10	06.20	04.10		Cable damaged & Incoming AB Switch Fixed & Moving Contacts replaced	
18	Medchal	Medicity	IDA	11KV	Medchal	05.00	15.25	10.25		Breaker Mechanism Problem & Backfeeding arranged from 11KV Venkateshwaragutta feeder from 33/11 KV Rajabollaram SS at 09:55	
19	Medchal	Yellampet	IDA Yellampet	11KV	Medchal	08.05	10.25	02.20		11KV Line Cut & Tree Branches fallen at near PHI Company	
20	Medchal	Kandlakoya	KV Reddy Nagar	11KV	Medchal	14.20	16.50	02.30		11KV Line AB Switch Opened at Indian Oil Petrol Pump (20% Charged)	
21	Hyderabad South	C.R.P.F	Balapur	11KV	Charminar	03.15	04.25	01.10	EL	Big tree fallen on lines & Lines snapped at Omar Colony (4Nos. DTRs kept off at Omar Colony)	
22	Hyderabad South	Malakpet	Chaderghat	11KV	Asmanghad	05.10	06.20	01.10	All Indication	No Visible Fault	
23	Hyderabad South	Malakpet	Chaderghat	11KV	Asmanghad	09.20	11.05	01.45	All Indication	8Nos. Jumpers burnt out near Chaderghat PS	

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
24	Hyderabad South	Miralam	Kalapather	11KV	Charminar	18.05	20.35	02.30	EL	Cable fault	
25	Hyderabad South	Hyderguda	Jana Priya OH	11KV	Charminar	21.09	23.49	02.40	EL	2Nos. Pin Insulators flash over at Jana Priya (2Nos. DTRs kept off)	
26	Hyderabad North	Nehru Nagar	Hari Hara Kala Bhavan	11KV	Paradise	21.29	22.30	01.01	All Indication	No Visible Fault	
27	CYBER CITY	Chanda nagar	Madinaguda	11KV	GACHIBOWLI	00.30	03.00	02.30	EL	Insulator failed & replaced at NSK Apartment	
28	RAJENDRA NAGAR	Kattedan-1	Gangotri	11KV	RAJENDRA NAGAR	01.21	03.02	01.41	EL	CP/PT failed at Plastic Company, Amma Garden backside	
29	CYBER CITY	Balaji Nagar	Moosapet	11KV	KONDAPUR	03.20	04.25	01.05	EL/OL	Tree Fallen on line & removed at MIG-907	
30	RAJENDRA NAGAR	ICAR	Rajendra Nagar	11KV	RAJENDRA NAGAR	05.25	07.11	01.46	OL	Tree Fallen on Line & Removed at Kallu Compound, Andhra Bank	
31	SAROOR NAGAR	Mother Dairy	Swathi Residency	11KV	SAROOR NAGAR	15.35	16.45	01.10	EL/OL	11KV Polymer Disc Failed & Replaced Opposite Swathi Residency	
32	SAROOR NAGAR	Mother Dairy	Seetharampuram	11KV	SAROOR NAGAR	19.30	21.10	01.40	EL/OL	11KV Pin insulator failed & replaced at kolanshivareddy colony	
33	Siddipet	Mallaram	Sikindlapur	11KV	Siddipet	11.44	12.06	00.22		B/D 11kv line cut	
34	Siddipet	Mirdoddy	AGL	11KV		06.49	07.17	00.28		B/D Ic no. 5622	

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
35	Siddipet	MULUGU	SARSAM PALLY(LC.NO:12728) VENKATESH .JLM	11KV	Gajwel	00.00	09.53	09.53		DISC FAILED	
36	Siddipet	ADIVIMAZID PALLY	ADIVIMAZID PALLY(LC.NO:42308) NAVEEN.ART	11KV		00.00	07.00	07.00		DISC FAILED	
37	Siddipet	VANTIMAMIDI	ZAPTHISINGAIPALLY(LC .NO:24371) SRINIVASREDDY.CL	11KV		00.00	08.50	08.50		TREE BRANCHES FALLEN ON THE 11KV LINE	
38	Siddipet	RAMSAGAR	RAMSAGAR(LC.NO:4235) VENKATRAJ.JLM	11KV		00.00	07.00			DISC FAILED	