

**Status Report on Breakdowns (Urban / Rural)****Urban**

| S.No | Circle       | No.of Feeders Existing Urban |             | Breakdowns occurred during the day |          | Attended during the day |          | Time taken for restoring the supply |          |                                |          | Remarks (Pending) |
|------|--------------|------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
|      |              | 33KV                         | 11KV        | 33KV                               | 11KV     | 33KV                    | 11KV     | Rectified (Within 24 Hours)         |          | Not Rectified (Above 24 Hours) |          |                   |
|      |              |                              |             |                                    |          |                         |          | 33KV                                | 11KV     | 33KV                           | 11KV     |                   |
| 1    | MBN          | 18                           | 107         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 2    | NLG          | 22                           | 358         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 3    | MDK          | 97                           | 359         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 4    | SDPT         |                              |             | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        | 0                 |
| 5    | RR(S)        | 53                           | 234         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 6    | RR(N)        | 54                           | 550         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 7    | RR(E)        | 168                          | 403         | 0                                  | 1        | 0                       | 1        | 0                                   | 1        | 0                              | 0        |                   |
| 8    | Hyd          | 194                          | 1044        | 0                                  | 2        | 0                       | 2        | 0                                   | 2        | 0                              | 0        |                   |
|      | <b>Total</b> | <b>606</b>                   | <b>3055</b> | <b>0</b>                           | <b>3</b> | <b>0</b>                | <b>3</b> | <b>0</b>                            | <b>3</b> | <b>0</b>                       | <b>0</b> |                   |

**Rural**

| S.No | Circle             | No.of Feeders Existing Rurals |             | Breakdowns occurred during the day |          | Attended during the day |          | Time taken for restoring the supply |          |                                |          | Remarks (Pending) |
|------|--------------------|-------------------------------|-------------|------------------------------------|----------|-------------------------|----------|-------------------------------------|----------|--------------------------------|----------|-------------------|
|      |                    | 33KV                          | 11KV        | 33KV                               | 11KV     | 33KV                    | 11KV     | Rectified (Within 24 Hours)         |          | Not Rectified (Above 24 Hours) |          |                   |
|      |                    |                               |             |                                    |          |                         |          | 33KV                                | 11KV     | 33KV                           | 11KV     |                   |
| 1    | MBN                | 107                           | 849         | 1                                  | 0        | 1                       | 0        | 1                                   | 0        | 0                              | 0        |                   |
| 2    | NLG                | 144                           | 988         | 0                                  | 2        | 0                       | 2        | 0                                   | 2        | 0                              | 0        |                   |
| 3    | MDK                | 107                           | 933         | 1                                  | 2        | 1                       | 2        | 1                                   | 2        | 0                              | 0        |                   |
| 4    | SDPT               |                               |             | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        | 0                 |
| 5    | RR(S)              | 58                            | 396         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 6    | RR(N)              | 38                            | 114         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
| 7    | RR(E)              | 22                            | 133         | 0                                  | 0        | 0                       | 0        | 0                                   | 0        | 0                              | 0        |                   |
|      | <b>Total</b>       | <b>476</b>                    | <b>3413</b> | <b>2</b>                           | <b>4</b> | <b>2</b>                | <b>4</b> | <b>2</b>                            | <b>4</b> | <b>0</b>                       | <b>0</b> |                   |
|      | <b>Grand Total</b> | <b>1082</b>                   | <b>6468</b> | <b>2</b>                           | <b>7</b> | <b>2</b>                | <b>7</b> | <b>2</b>                            | <b>7</b> | <b>0</b>                       | <b>0</b> |                   |

**TSSPDCL - LMRC / Corporate office****Circle-wise 33KV Breakdowns****Date: 10.09.2021**

| S.No | Circle       | Name of 132/33KV SS | Name of 33 KV Feeder | Vol  | Name of the Division | From  | To    | Duration | Relay Indication | Cause of Breakdown                               | Sub Stations Effected | Alternate Supply Arranged   |
|------|--------------|---------------------|----------------------|------|----------------------|-------|-------|----------|------------------|--|-----------------------|---|
| 1    | Mahabubnagar | Maddur              | Damargidda           | 33KV | Narayanpet           | 15.30 | 15.55 | 00.25    | E/L              | 33KV insulator failed near 132KVSS line crossing |                       | Alternate Supply Arranged from 33KV Kankurthy feeder at 15:55Hrs. |
| 2    | Sangareddy   | Gummadidala         | GPSS-I               | 33KV | Patancheru           | 08.45 | 10.05 | 01.20    |                  | BD due to Jumper cut                             |                       |   |

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.09.2021

| S. No | Circle       | Name of 33/11KV SS | Name of 11 KV Feeder | Vol  | Name of the Division | From  | To    | Duration | Relay Indication | Cause of Breakdown                 | Alternate Supply Arranged |
|-------|--------------|--------------------|----------------------|------|----------------------|-------|-------|----------|------------------|------------------------------------|---------------------------|
| 1     | Nalgonda     | Aitipamula         | Duginevelli          | 11KV | Nalgonda             | 10.30 | 12.15 | 01.45    | EL               | 11KV Line Jumper Cut               |                           |
| 2     | Nalgonda     | Narketpally        | Mallekunta           | 11KV | Nalgonda             | 11.30 | 13.45 | 02.15    | EL               | 11KV Line Jumper Cut               |                           |
| 3     | Sangareddy   | Bollaram - II      | Vipla                | 11KV | Patancheru           | 16.27 | 17.02 | 00.35    |                  | BD due to Jumper cut               |                           |
| 4     | Siddipet     | MOBHARASPU<br>R    | MOBHARASPUR          | 11KV | Gajwel               | 13.00 | 13.45 | 00.45    |                  | INSULATOR FAILED                   |                           |
| 5     | Hyd-South    | Kandikal Gate      | G.M.Chowni           | 11KV | Charminar            | 06.20 | 07.50 | 01.30    | EL,OL            | AB Cable damaged at Boiguda Bridge |                           |
| 6     | Hyd-Central  | Golconda           | Q.Q.Toombs           | 11KV | Mehdipatnam          | 06.45 | 08.20 | 01.35    | EL,OL-Rph        | Jumper cut on 1st line AB Switch   |                           |
| 7     | SAROOR NAGAR | RR Court           | Chitra Layout        | 11KV | SAROOR NAGAR         | 01.00 | 02.11 | 01.11    | EL/OL            | No Visible fault                   |                           |