

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	0	0	0	0	0	0	0	
6	RR(N)	54	550	0	0	0	0	0	0	0	0	
7	RR(E)	168	403	0	1	0	1	0	1	0	0	
8	Hyd	194	1044	0	2	0	2	0	2	0	0	
	Total	606	3055	0	3	0	3	0	3	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	0	1	0	1	0	0	0	
2	NLG	144	988	0	2	0	2	0	2	0	0	
3	MDK	107	933	1	2	1	2	1	2	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	Total	476	3413	2	4	2	4	2	4	0	0	
	Grand Total	1082	6468	2	7	2	7	2	7	0	0	

TSSPDCL - LMRC / Corporate office**Circle-wise 33KV Breakdowns****Date: 10.09.2021**

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	Mahabubnagar	Maddur	Damargidda	33KV	Narayanpet	15.30	15.55	00.25	E/L	33KV insulator failed near 132KVSS line crossing		Alternate Supply Arranged from 33KV Kankurthy feeder at 15:55Hrs.
2	Sangareddy	Gummadidala	GPSS-I	33KV	Patancheru	08.45	10.05	01.20		BD due to Jumper cut		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 10.09.2021

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Nalgonda	Aitipamula	Duginevelli	11KV	Nalgonda	10.30	12.15	01.45	EL	11KV Line Jumper Cut	
2	Nalgonda	Narketpally	Mallekunta	11KV	Nalgonda	11.30	13.45	02.15	EL	11KV Line Jumper Cut	
3	Sangareddy	Bollaram - II	Vipla	11KV	Patancheru	16.27	17.02	00.35		BD due to Jumper cut	
4	Siddipet	MOBHARASPU R	MOBHARASPUR	11KV	Gajwel	13.00	13.45	00.45		INSULATOR FAILED	
5	Hyd-South	Kandikal Gate	G.M.Chowni	11KV	Charminar	06.20	07.50	01.30	EL,OL	AB Cable damaged at Boiguda Bridge	
6	Hyd-Central	Golconda	Q.Q.Toombs	11KV	Mehdipatnam	06.45	08.20	01.35	EL,OL-Rph	Jumper cut on 1st line AB Switch	
7	SAROOR NAGAR	RR Court	Chitra Layout	11KV	SAROOR NAGAR	01.00	02.11	01.11	EL/OL	No Visible fault	