

Status Report on Breakdowns (Urban / Rural)**Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	1	0	1	0	1	0	1	
6	RR(N)	54	550	0	3	0	3	0	3	0	3	
7	RR(E)	168	403	0	2	0	2	0	2	0	2	
8	Hyd	194	1044	0	0	0	0	0	0	0	0	
	Total	606	3055	0	6	0	6	0	6	0	6	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	1	0	1	0	1	0	1	0	
2	NLG	144	988	0	0	0	2	0	0	0	0	
3	MDK	107	933	2	0	2	0	2	0	2	0	
4	SDPT			0	3	0	3	0	3	0	3	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	Total	476	3413	3	3	3	5	3	3	3	3	
	Grand Total	1082	6468	3	9	3	11	3	9	3	9	

TSSPDCL - LMRC / Corporate office**Circle-wise 33KV Breakdowns****Date: 11.09.2021**

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Chinnamaroor	Weepangandla	33KV	Wanaparthu	19.30	19.40	00.10	E/L	Due to Rain	-	
2	Sangareddy	Zaheerabad	Hadnoor	33KV	Zaheerabad	16.55	17.55	01.00		B/D Due to tree Branch fallen on the line		
3		Gummadidala	Gummadidala	33KV	Patancheru	05.40	06.50	01.10		B/D Due to Conductor Snapped		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 11.09.2021

S. No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Siddipet	Kammarlapally	Kothapally	11KV	Siddipet	19.30	21.40	02.10		B/D - 11KV wire cut	-
2	Siddipet	Gowraram SS	Pamulaparthi feeder LC.No.26624	11KV	Gajwel	10.50	12.52	02.02		11KV Jumper cut	-
3	Siddipet	Medinipur SS	Boppaipally Feeder LC.No28411	11KV		15.50	17.50	02.00		11KV Jumper cut & LT line work	-
4	Habsiguda	Uppal	Ghatkesar	11KV	Habsiguda	08.31	09.46	01.15		HT/LT Line cut at Tea Time Opposite	-
5	Medchal	Kandlakoya	KV Reddy Nagar	11KV	Medchal	05.40	06.56	01.16		Tree branch fallen on the 11KV Line at Kaveri Seeds	-
6	Medchal	Gowdavelly	IDA Gowdavelly	11KV	Medchal	09.00	09.20	00.20		Breaker Mechanical Problem(Backfeeding arranged from Basaragadi feeder)	-
7	Medchal	Medchal	CMR	11KV	Medchal	16.15	17.30	01.15		Line petrolling No fault	-
8	SAROOR NAGAR	Tattiannaram	Indu aranya apartment	11KV	SAROOR NAGAR	03.48	06.24	02.36	EL	11KV Pin Insulator failed & replaced at Corporation bhavan	-
9	RAJENDRA NAGAR	Gandamguda	Hydershakote	11KV	RAJENDRA NAGAR	10.42	12.28	01.46	EL	11KV UG Cable Failed and rectified at Kings Bar	on 11KV Military-2 Feeder From 33KV Ibrahimbagh SS