

Status Report on Breakdowns (Urban / Rural)

Urban

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	2	0	2	0	2	0	0	
6	RR(N)	54	550	0	1	0	1	0	1	0	0	
7	RR(E)	168	403	0	4	0	4	0	4	0	0	
8	Hyd	194	1044	0	0	0	0	0	0	0	0	
	Total	606	3055	0	7	0	7	0	7	0	0	

Rural

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	2	0	2	0	2	0	0	0	
2	NLG	144	988	2	4	2	4	2	4	0	0	
3	MDK	107	933	0	2	0	2	0	2	0	0	
4	SDPT			1	1	1	1	1	1	0	0	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	Total	476	3413	5	7	5	7	5	7	0	0	
	Grand Total	1082	6468	5	14	5	14	5	14	0	0	

TSSPDCL - LMRC / Corporate office

Circle-wise 33KV Breakdowns

Date: 13.09.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Sub Stations Effected	Alternate Supply Arranged
1	MBNR	Mahabubnagar	Jadcherla	33KV	Mahabubnagar	16.50	17.10	00.20	OL	Due to Rain	Alternate Supply Arranged from 33KV Gangapur at 17:10Hrs	
2	MBNR	Narayanpet	Kotakonda	33KV	Narayanpet	17.15	19.20	02.05	OL	Tree Follen on the line near Apakpally	No	
3	Nalgonda	Nalgonda	Pajjur	33KV	Nalgonda	08.30	11:35	3:05	EL/OL	33Kv Moument Falte		
4	Nalgonda	Thurkapally	Thurkapally	33KV	Nalgonda	08.50	10:18	1:28	E/L	11KV Line Jumper Cut		
5	Siddipet	Shanigaram	Bejjanki	33KV	Husnabad	03.25	09.10	05.45		BD (NO Fuailt)		

TSSPDCL - LMRC / Corporate office

Circle-wise 11KV Breakdowns

Date: 13.09.2021

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	Habsiguda	Uppal	Adarsh Nagar	11KV	Habsiguda	16.50	18.02	01.12		Tree Baranches Fallen 11KV Line at Adarsh Nagar Road No.9	
2	Habsiguda	Peerzadiguda	Shankar Nagar	11KV	Keesara	16.34	17.34	01.00		Tree fallen 11KV Line Shankar Nagar	
3	Habsiguda	Uppal	Adarsh Nagar	11KV	HABSIGUDA	16.50	18.02	01.12	EL	Due to Rain,Tree Branch Fallen on Line and Removed at Road no-9,Adarsh Nagar	
4	Medchal	Aliabad	LGM Pet	11KV	Medchal	10.35	11.05	00.30	BD	Copper Patti Cut & Replaced at SC Colony, LGM Pet	
5	Nalgonda	Thurkapally	Thurkapally	11KV	Nalgonda	08.50	10.18	01.28		11KV Line Jumper Cut	
6	Siddipet	Komuravelly	Komuravelly Agl	11KV	Husnabad	19.16	21.00	01.44		11 kv Jumper open	
7	Sangareddy	Sadasivpet	TSM	11KV	Sangareddy	15.05	19.20	04.15		BD due to 3No.s Disks failed	
8	Sangareddy	EPIP-III	Tyechi Diecast	11KV	Sangareddy	15.48	16.25	00.37		BD due to Tree branch fallen on line	
9	Suryapet	Indl.Esate	Vijaya colony	11KV	Suryapet	15.30	17.00	01.30		Insulator failed	
10	Suryapet	Nadigudem	Krishnanagar	11KV	Huzurnagar	07.50	09.05	01.15		11 KV LINE SNAPPED	
11	Yadadri	Bhongir	Meenanagar	11KV	Bhongir	21.15	22.54	01.39		11kv Line napped near genius high school Bhongir Town	
12	RAJENDRA NAGAR	Green witch	Regal garden	11KV	RAJENDRA NAGAR	10.25	12.40	02.15	EL/OL	CT Clamp cut & fallen on panther at Yard	
13	RAJENDRA NAGAR	Gaganpahad	Silicon rubber	11KV	RAJENDRA NAGAR	16.50	19.00	02.10	EL/OL	Due to Rain,11KV Cable Short Circuited and Rectified at Padmavathi Plywood	
14	SAROOR NAGAR	Kothapet	Saroor Nagar	11KV	SAROOR NAGAR	16.01	17.34	01.33	EL/OL	Due to Rain,11KV Insulator Flashover and Replaced at B.C Hostel,Saroor Nagar	