

**Status Report on Breakdowns (Urban / Rural)****Urban**

S.No	Circle	No.of Feeders Existing Urban		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	18	107	0	0	0	0	0	0	0	0	
2	NLG	22	358	0	0	0	0	0	0	0	0	
3	MDK	97	359	0	0	0	0	0	0	0	0	
4	SDPT			0	0	0	0	0	0	0	0	0
5	RR(S)	53	234	0	0	0	0	0	0	0	0	
6	RR(N)	54	550	3	7	3	7	3	7	0	0	
7	RR(E)	168	403	0	1	0	1	0	1	0	0	
8	Hyd	194	1044	0	12	0	12	0	12	0	0	
	<b>Total</b>	<b>606</b>	<b>3055</b>	<b>3</b>	<b>20</b>	<b>3</b>	<b>20</b>	<b>3</b>	<b>20</b>	<b>0</b>	<b>0</b>	

**Rural**

S.No	Circle	No.of Feeders Existing Rurals		Breakdowns occurred during the day		Attended during the day		Time taken for restoring the supply				Remarks (Pending)
		33KV	11KV	33KV	11KV	33KV	11KV	Rectified (Within 24 Hours)		Not Rectified (Above 24 Hours)		
								33KV	11KV	33KV	11KV	
1	MBN	107	849	3	1	3	1	3	1	0	0	
2	NLG	144	988	0	5	0	5	0	5	0	0	
3	MDK	107	933	0	1	0	1	0	1	0	0	
4	SDPT			1	0	1	0	1	0	0	0	0
5	RR(S)	58	396	0	0	0	0	0	0	0	0	
6	RR(N)	38	114	0	0	0	0	0	0	0	0	
7	RR(E)	22	133	0	0	0	0	0	0	0	0	
	<b>Total</b>	<b>476</b>	<b>3413</b>	<b>4</b>	<b>7</b>	<b>4</b>	<b>7</b>	<b>4</b>	<b>7</b>	<b>0</b>	<b>0</b>	
	<b>Grand Total</b>	<b>1082</b>	<b>6468</b>	<b>7</b>	<b>27</b>	<b>7</b>	<b>27</b>	<b>7</b>	<b>27</b>	<b>0</b>	<b>0</b>	

## TSSPDCL - LMRC / Corporate office

## Circle-wise 33KV Breakdowns

Date: 20.09.2021

S.No	Circle	Name of 132/33KV SS	Name of 33 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Maddur	Vepoor	33KV	Narayanpet	18:15	19:25	1:10	EL&OL	33KV Line Fault	AB Switch open at Lingalshed village at 19:25Hrs
2	MBNR	Marikal	Koilkonda Water Grid	33KV	Narayanpet	19:41	20:30	0:49	O/L	33KV Line Fault	Alternate Supply Arranged to 33KV Devarkadra Feeder at 20:30Hrs
3	Siddipet	Gajwel	Pragnapur	33KV	Gajwel	1:00	12:30	12:30		BD ( Conductor Snapped )	
4	Medchal	132KV LGM Pet	33KV LGM Pet	33KV	Medchal	4:45	6:00	1:15		Incoming Supply failure from 132KV LGM Pet Backfeeding arranged from 33KV Ratnalayam feeder (132KV Malkaram) & Isolator failed at M.C. Pally (V)	
5	Medchal	132KV LGM Pet	33KV Aliabad	33KV	Medchal	3:53	8:14	4:21		Coconut tree branches fallen on 33KV OH Line at LGM Pet Main Road	
6	Medchal	132KV LGM Pet	33KV LGM Pet	33KV	Medchal	16:37	18:35	1:58		Tree Fallen on 33KV Line at Pokarana Company Backside	

Circle-wise 33KV Breakdowns

Date: 20.09.2021

7	Gadwal	leeza	TT Doddi	33KV	Gadwal	10.22	04.19	02.50		due to tree cutting near 132 kv ieeja	
---	--------	-------	----------	------	--------	-------	-------	-------	--	---------------------------------------	--

**TSSPDCL - LMRC / Corporate office**

**Circle-wise 11KV Breakdowns**

**Date: 20.09.2021**

S.No	Circle	Name of 33/11KV SS	Name of 11 KV Feeder	Vol	Name of the Division	From	To	Duration	Relay Indication	Cause of Breakdown	Alternate Supply Arranged
1	MBNR	Midjil	Veljal	11KV	Jadcherla	11:44	15:00	3:16		11KV Jumper Cut near Marlabaithanda	No
2	Nalgonda	Nakrekal	Market	11KV	Nalgonda	4:55	6:39	1:44	E/L	11Kv Jumper Cut	
3	Nalgonda	Junuthula	Pallipahad Feeder	11KV	Devarakonda	16.00	17.55	01.55	E/L	11Kv Pin Insulater Failed	
4	Sangareddy	Bollaram-II	Kottam	11KV	Patancheru	06.05	07.05	01.00		BD due to Jumper cut	
5	Suryapet	Akupamula	Singaram	11KV	Huzurnagar	3:00	6:45	3:45		11 KV LINE SNAPPED	
6	Suryapet	Sirikonda	Ravipahad	11KV	Huzurnagar	6:40	8:30	1:50		11 KV LINE SNAPPED	
7	Yadadri	Maryala	Mailaram	11KV	Bhongir	4:00	7:00	3:00		11kv Line Snpped near Narala Balreddy well	
8	Medchal	Medchal	IDA Kistapur	11KV	Medchal	17:04	19:30	2:26		Tree Fallen on 11KV Line at Need Engergy Kistapur Road	
9	Medchal	Town Medchal	Balaji Nagar	11KV	Medchal	16.47	18.10	01.23		No Fault	
10	Medchal	Medchal	Check Post	11KV	Medchal	16.10	18.40	02.30		Tree Fallen on LT Line at Subbaram Reddy Thota,Suthariguda Road	
11	Medchal	Medchal	Navadurga	11KV	Medchal	16.16	19.20	03.04		Tree Fallen on 11KV Line at Sleep well Opp	
12	Medchal	GP Pally	GP Pally	11KV	Medchal	17.30	18.35	01.05		11KV Brass Patti cut and replaced at Damping Yard,GP Pally	
13	Medchal	Aliabad	HBL	11KV	Medchal	17.58	19.00	01.02		Tree Fallen on 11KV Line at HBL Company	
14	Medchal	Medchal	IDA-I	11KV	Medchal	17.55	19.28	01.33		Tree Fallen on 11KV Line at Telephone office	
15	Hyderabad North	Lalaguda	Shanthi Nagar	11KV	Paradise	03.35	05.05	01.30	EL	11KV Lines touched to Ganesh Idol	
16	Hyderabad North	Monda Market	Dharma Kanta	11KV	Paradise	10.45	12.25	01.40	EL,OL	UG Cable fault at Gandhi Hospital	
17	Hyderabad South	Moosarambagh	A.B.Colony	11KV	Asmanghad	14.13	17.35	03.22	EL	Pin Insulator flash over at A.B.Colony Chowrastha	

18	Hyderabad South	Asmangadh	Saidabad Colony	11KV	Asmanghad	14.40	16.05	01.25	EL,OL-Yph	Pin Insulator flash over at Akther Residency	
19	Hyderabad South	Miralam	Amzathullah Bagh	11KV	Charminar	14.47	17.55	03.08	EL,OL	HT Conductor snapped at Mahaboob Dairy Farm	
20	Hyderabad South	Miralam	Teegala Kunta	11KV	Charminar	14.55	16.35	01.40	EL,OL	Pin Insulator flash over at Teegala Kunta	
21	Hyderabad South	Malakpet	M.M.H	11KV	Asmanghad	14.56	16.20	01.24	OL-Rph	Faulty loads of 11KV Osmanpura feeder	
22	Hyderabad South	Kandikal Gate	Naseeb Nagar	11KV	Charminar	15.05	16.25	01.20	EL	Bird fault on HT Lines at Flowers Shop	
23	Hyderabad South	Panjesha	Shajahan Hotel	11KV	Charminar	16.00	18.10	02.10	EL	Pin Insulator flash over at Sultan Shai Play Ground	
24	Hyderabad South	Malakpet B-Block	C-Quarters	11KV	Asmanghad	17.58	19.03	01.05	OL	Pin Insulator flash over at Hanuman Temple	
25	Hyderabad South	Sultan Bazar	Sultan Bazar	11KV	Begumbazar	22.04	23.12	01.08	EL,OL-Rph	Tree branches fallen on lines at Sulabh Complex	
26	Hyderabad North	Seethaphalmandi	Warasiguda	11KV	Paradise	22.20	23.45	01.25	EL,OL-Bph	Faulty loads of 11KV Medibavi feeder (2No. DTR's kept off)	
27	SAROOR NAGAR	Hayath nagar	Hayath nagar	11KV	SAROOR NAGAR	16.00	17.30	01.30	OL	11KV Pin Insulator failed at Govt school,Shanthivanam township	